

Detroit District Operations Office P.O. Box 1027 Detroit, MI 48231-1027 (313) 226-6797 FAX - (313) 226-3519

## Notice to Navigation Interests

Notice No. L07-37 Date: 23 JULY 2007

Waterway: LAKE HURON Location: MICHIGAN

**CELRE-OT-T** 


## CONDITION OF FEDERAL NAVIGATION CHANNEL TAWAS BAY HARBOR

- 1. Surveys performed during July 2007 indicate shoaling in the Federal navigation channel at Tawas Bay Harbor, Michigan. As shown on reverse. The surveys are available on our web site. Our internet address is: <a href="http://www.lre.usace.army.mil/who/operationsofficehomepage/">http://www.lre.usace.army.mil/who/operationsofficehomepage/</a>
- 2. Mariners are urged to use extreme caution in the area.
- 3. Questions regarding this notice may be directed to our Operations Office.

WILLIAM J. LEADY Lieutenant Colonel, U.S. Army District Commander

## Notice to the Postmaster:

It is requested that the above notice be conspicuously and continuously posted until November 30, 2007.



The information depicted on this map represents the results of surveys made on the dates indicated and can only be considered as indicating the conditions existing at that time.

Surveys taken: July 2007

Shoals indicate least available depth below LWD

TAWAS BAY HARBOR, MICHIGAN

CONDITION OF CHANNEL

ISSUED: 23 July 2007

U.S. Army Engineer District, Detroit

0tawas.bmp